



Insulation stripper PG



1- Longitudinal cut

Position the PG BT pliers as shown to the desired length. Tighten the pliers until the cutting wheel penetrates onto stop rollers. Pull the pliers along the length to be stripped in the direction shown by the arrow.





2- Circular cut

Position the PG BT pliers at the end of the longitudinal cut. Close the pliers on the cables pressing slightly to ensure penetration of the cutting wheels. Rotate the pliers back and forth by a third of revolution



3- Removal of sheath

Use the two end blades to separate the sheath.





- ⚠ The tools must be used when the cable is out of tension by skilled workers who are competent in cable preparation and know about electrical phenomenons.
- ⚠ Wearing anti-cut gloves is obligatory.
- ⚠ Clean the tools after each utilization.

Dénudeur PG



1- Coupe longitudinale

 Présenter la pince sur le câble en position de coupe longitudinale et tirer dans le sens de la flèche.





2- Coupe circulaire

 Présenter la pince sur le câble en position de coupe circulaire et tourner dans le sens des flèches.



3- Ouverture de la gaine

 Utiliser les griffes de la pince pour enlever la gaine du câble.



- ⚠ Les outils doivent être utilisés lorsque le câble est hors tension par du personnel qui dispose de compétences en matière de préparation des câbles et de connaissances sur les phénomènes électriques.
- ⚠ Port de gants anti-coupure obligatoire.
- ⚠ Nettoyage de l'outil impératif après utilisation.